

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Patent No. : US 7,706,769 B2

Issue Date : April 27, 2010

Inventor : Richard Perkins

Docket No. : 853463.466USPC

Date : November 16, 2010

Mail Stop Certificate of Correction  
Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents:

A certificate of correction is respectfully requested in the above-identified patent.

The following errors have been made:

In the claims, column 5, issued claim 1, line52, “RSSI<minimum signal strength;” is incorrect. As set forth in the Amendment filed September 22, 2009 with the United States Patent and Trademark Office, the correct line should read, --RSSI>minimum signal strength;--.

In the claims, column 6, issued claim 5, line 34, “RSSI<minimum signal strength;” is incorrect. As set forth in the Amendment filed September 22, 2009 with the United States Patent and Trademark Office, the correct line should read, --RSSI>minimum signal strength;--. Issued claim 5 appears as claim 10 during prosecution.

Attached is the certificate of correction, which indicates the corrections to be made, by reference to the column and line numbers in the printed patent. Because the errors were made by the Patent Office, no fee is necessary. However if the errors are determined to be our errors, the Director is hereby authorized to charge payment of any fees associated with this communication to Deposit Account No. 19-1090.

Respectfully submitted,  
SEED Intellectual Property Law Group PLLC

/E. Russell Tarleton/

E. Russell Tarleton  
Registration No. 31,800

ERT:ccj

Enclosure:

Certificate of Correction

SEED Intellectual Property Law Group PLLC  
701 Fifth Avenue, Suite 5400  
Seattle, Washington 98104-7092  
Phone: (206) 622-4900  
Fax: (206) 682-6031

1747970\_1.DOCX

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO : US 7,706,769 B2

APPLICATION NO. : 10/560,852

DATED : April 27, 2010

INVENTOR : Richard Perkins

It is certified that errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 5

Claim 1, Line 52, "RSSI<minimum signal strength;" should read as --RSSI>minimum signal strength;--.

Column 6

Claim 5, Line 34, "RSSI<minimum signal strength;" should read as --RSSI>minimum signal strength;--.

MAILING ADDRESS OF SENDER:

E. Russell Tarleton

Seed Intellectual Property Law Group PLLC

701 Fifth Avenue, Suite 5400

Seattle, Washington 98104

PATENT NO. US 7,706,769 B2

No. of additional copies: 0

SEND TO: Attention Certificate of Corrections Branch, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450